# Field Comparison of Five Pavement Marking Removal Technologies

# **FINAL REPORT**

# **Prepared For:**

Utah Department of Transportation Research Division

# Submitted by:

Ken Berg, P.E., Development Engineer

# **Authored by:**

Ken Berg, P.E., Development Engineer Stan Johnson, Rotational Engineer

January 2009

The authors alone are responsible for the preparation and accuracy of the information, data, analysis, discussions, recommendations, and conclusions presented herein. The contents do not necessarily reflect the views, opinions, endorsements, or policies of the Utah Department of Transportation of the US Department of Transportation. The Utah Department of Transportation makes no representation or warranty of any kind, and assumes no liability therefore.

## **ACKNOWLEDGEMENTS**

The author wishes to acknowledge the following for their contributions:

Rukhsana Lindsey—Director of Research, Utah Department of Transportation

Dan Betts, UDOT Region 2 Operations Supervisor

**UDOT Region 2 Maintenance Forces** 

Robert Miles, UDOT, Standards & Pre-construction Engineer

Dry Ice Blasting Service (D.I.B.S.)

**Interstate Striping Services** 

Dunn-Rite Lines (formerly COMAX)

Waterblasting Technologies

DLP Construction Co.

1. Report No.	2. Government Aco	cession No.	3. Recipient's Catalog	No.		
UT- 08.12						
01-00.12						
4. Title and Subtitle	•		5. Report Date			
FIELD COMPARISON OF FI	VE PAVEME	ENT MARKING	Jan. 2009			
REMOVAL TECHNOLOGIE	S		6. Performing Organization Code			
			N/A			
7. Author			8. Performing Organiz	zation Report No.		
Ken Berg, P.E.			N/A			
Stan Johnson, E.I.T						
9. Performing Organization Name and Address			10. Work Unit No.			
Utah Department of Transporta	ntion		N/A			
4501 South 2700 West			11. Contract or Grant No.			
Salt Lake City, Utah 84114-84	-10		N/A			
3,						
12. Sponsoring Agency Name and Address			13. Type of Report &	Period Covered		
Utah Department of Transport	ation		FINAL			
4501 South 2700 West	4501 South 2700 West		14. Sponsoring Agency Code			
Salt Lake City, Utah 84114-84	-10					
15. Supplementary Notes			-1			
Prepared by the Utah Departm	ent of Transpo	ortation				
16. Abstract						
This paper reports on the effective	eness of five d	ifferent methods of	pavement markin	ng removal, including		
diamond grinding, carbide grinding	ng, hydraulic b	plasting, dry ice blas	sting, and soda bl	asting. The measures of		
effectiveness used were a quantitative measure of speed of removal and a subjective discussion of surface						
preparation and the pros and cons	of each techn	ology,				
17. Key Words	18. Distribution Statement 2			23. Registrant's Seal		

17. Key Words		18. Distribution State	ment	23. Registrant's Seal
Pavement marking removal		UDOT Research Division 4501 South 2700 West-box 148410 Salt Lake City, Utah 84114		N/A
19. Security Classification	20. Security Classification	21. No. Of Pages	22. Price	
(of this report)	(of this page)		N/A	
Unclassified	Unclassified	27		

## TABLE OF CONTENTS

ACKNOWLEDGEMENTS	iii
EXECUTIVE SUMMARY	vii
1.0 INTRODUCTION	8
2.0 RESEARCH METHODS	8
3.0 APPLICATION OF TECHNOLOGIES	9
4.0 DATA COLLECTION	9
4.1 Quantitative data	9
4.2 VISUAL DATA	11
4.2.1 Dry ice Blasting	11
4.2.2 Carbide Grinding	
4.2.3 Diamond Bit Grinding	13
4.2.4 Hydraulic blasting	14
4.2.5 Soda Blasting	16
5.0 DATA EVALUATION/ANALYSIS	17
6.0 CONCLUSIONS	17
6.1.1 Dry Ice Blasting	18
6.1.2 Carbide Grinding	
6.1.3 Diamond Bit (COMAX) Grinding	18
6.1.4 Stripe Hog Hydroblaster	
6.1.5 Soda Blasting	18
7.0 RECOMMENDATIONS/IMPLEMENTATIONS	19
APPENDIX A	20
APPENDIX C	22
APPENDIX D	23
APPENDIX E	24

## LIST OF FIGURES AND TABLES

(Figure 1)	Location map	.8
(Table 1)	Removal rates on chip seal, fastest to slowest, in descending order	10
(Table 2)	Removal rates on concrete, fastest to slowest in descending order	10
(Figure 2)	Results of dry ice blasting on chip seal using a hand-held wand (note the marking material	l
	is completely removed but the surface is pitted. The dry ice dissipated into the air leaving	
	no residuals.)	11
(Figure 3)	Results of dry ice blasting technique on concrete (note the marking material is completely	
	removed and the surface is free from pitting with a faint shadow line.)	11
(Figure 4)	Results of carbide grinding technique on chip seal (note the marking material is completel	y
	removed but a shadow line still remains)	12
(Figure 5)	Results of carbide grinding technique on concrete (note the marking material is partially	
	removed and a shadow line still remains)	12
(Figure 6)	Results of diamond grinding technique on chip seal (note the marking material is removed	d
	and a shadow line remains)	13
(Figure 7)	Results of diamond bit grinding technique on concrete (note the marking material is	
	removed and a shadow line remains)	13
(Figure 8)	Results of hydraulic blasting on chip seal while still wet	14
(Figure 9)	Results of hydroblaster technique on concrete while still partially wet. Note the marking	
	material is completely removed and a shadow line still remains)	15
(Figure 11)	Results of soda blasting technique on chip seal. Note marking material seems completely	
	removed and a shadow line still remains. Note, also, the residual dust on the	
	road surface	16
(Figure 12)	Results of soda blasting technique on concrete. Note the marking seems completely	
	removed and a faint shadow line still remains. Note, also, the residual dust on the road	
	surface	17

#### **EXECUTIVE SUMMARY**

A demonstration of five different pavement marking removal systems was presented in May of 2008. The five methods were diamond grinding, carbide grinding, hydraulic blasting, dry ice blasting, and soda blasting. Each of the technologies was applied to sections of chip seal pavement, and Portland cement concrete (PCC) pavement.

The two grinding technologies are still the most effective in removing lines quickly and providing a clean, prepared surface for marking installation. The soda and dry ice technologies should be investigated for possible use where space is limited or other specialized removal needs are present, but are not yet comparable to the production rates of the grinding or water blasting equipment. The amount of dust generated by the soda blasting technique should be factored into a manager's decision to use that technology.

The water blasting technology is the most effective at marking removal with the least amount of damage to the pavement and should be investigated for possible use by the Department.

#### 1.0 INTRODUCTION

On May 6, 2008 a field comparison of four different pavement marking removal technologies was conducted on SR-202. SR-202 is located between the town of Garfield and the Salt Air Historic Beach near Magna, Utah (Figure 1). The road has a chip seal surface that was striped two years ago with state specification waterborne paint. The road was closed from 12:00 noon until 4:00 PM. A fifth technology, soda blasting, was later demonstrated on June 23, 2008.



(Figure 1) Location map

Representatives from UDOT, FHWA Utah Division Office, Salt Lake County, Salt Lake City and the Airport Authority were in attendance.

#### 2.0 RESEARCH METHODS

The objectives of the test were to compare the effectiveness of the removal technologies and the relative visibility of the remaining shadow lines.

Personnel from the Research Division of the Utah Department of Transportation (UDOT) attended the demonstration and video recorded the processes and measured the removal times.

#### 3.0 APPLICATION OF TECHNOLOGIES

The five technologies used are as follows:

Diamond grinding (Appendix A)

Carbide grinding (Appendix B)

Hydraulic blasting (Appendix C)

Dry Ice blasting (Appendix D)

Soda blasting (Appendix E)

Each of the technologies was used on a selected stretch of chip sealed pavement, and then on a selected stretch of Portland Cement Concrete (PCC) pavement.

The vehicle-borne technologies (grinding and hydraulic blasting) were tested on 650' sections of pavement that were marked with two-year old, white waterborne shoulder paint placed on a chip seal. On concrete, the test section was a 300' stretch of waterborne paint placed over the top of existing white, epoxy shoulder paint.

The blasting technologies (dry ice and soda) were tested on fifty-foot sections of the same pavement on which the vehicle-borne technologies were applied.

#### 4.0 DATA COLLECTION

Quantitative data included the length of pavement marking removed per unit time, and the depth and width of marking removal when used on chip seal.

The qualitative data collected is in the form of images that were exported from the video.

#### 4.1 Quantitative data

Table 1 summarizes the speed of each of the 5 removal technologies, in descending order, on the chip seal surface. The tests on chip seal were conducted on the north bound shoulder of SR-202. The tests on concrete were conducted on the eastbound off-ramp of I-80 as it turns onto SB SR-202. Both locations were tested on 5/6/08.

On 6/23/08 the soda blasting technology on the chip sealed surface was tested on the north bound shoulder of SR-202 using three separate nozzles. The tests on concrete were conducted on the I-80 west bound on ramp at the 7200 South interchange using only one nozzle.

Removal Rates on Chip Seal						
Process	Depth Setting	Head Width (in.)	Head Type	Distance (ft.)	Time (sec.)	Ave. Speed (ft./sec.)
Carbide Grind	20 mils	6	Grinding heads	650	295	2.20
Diamond Grind	20 mils	5.5	Grinding heads	650	336	1.93
Hydro Blast	none, floats on surface	12	Blasting head	650	356	1.83
Soda Blast-3rd	none, held above surface	12	Hand-held wand	20	139	0.14
Soda Blast-2nd	none, held above surface	n/a	Hand-held wand	20	193	0.10
Soda Blast-1st	none, held above surface	n/a	Hand-held wand	20	252	0.08
CO <sub>2</sub> Blast	none, held above surface	n/a	Hand-held wand	4	240	0.02

(Table 1) Removal rates on chip seal, fastest to slowest, in descending order

Removal Rates on Concrete						
Process	Depth Setting	Head Width	Head Type	Distance (ft.)	Time (sec.)	Ave. Speed (ft./sec.)
Carbide Grind	20 mils	(in.) 6	Grinding heads	300	222	1.35
Diamond Grind	20 mils	5.5	Grinding heads	300	313	0.96
Hydro Blast	none, floats on surface	12	Blasting head	300	399	0.75
Soda Blast	none, held above surface	n/a	Hand-held wand	8.66	372	0.02
CO₂ Blast	none, held above surface	n/a	Hand-held wand	1.33	120	

(Table 2) Removal rates on concrete, fastest to slowest in descending order


#### 4.2 Visual data

Below is the visual data gathered:

#### 4.2.1 Dry ice Blasting



(Figure 2) Results of dry ice blasting on chip seal using a hand-held wand (note the marking material is completely removed but the surface is pitted. The dry ice dissipated into the air leaving no residuals.)



(Figure 3) Results of dry ice blasting technique on concrete (note the marking material is completely removed and the surface is free from pitting with a faint shadow line.)

## 4.2.2 Carbide Grinding



(Figure 4) Results of carbide grinding technique on chip seal (note the marking material is completely removed but a shadow line still remains)



(Figure 5) Results of carbide grinding technique on concrete (note the marking material is partially removed and a shadow line still remains)

## 4.2.3 Diamond Bit Grinding



(Figure 6) Results of diamond grinding technique on chip seal (note the marking material is removed and a shadow line remains)



(Figure 7) Results of diamond bit grinding technique on concrete (note the marking material is removed and a shadow line remains)

## 4.2.4 Hydraulic blasting



(Figure 8) Results of hydraulic blasting on chip seal while still wet.



(Figure 9) Results of hydraulic blasting on chip seal after drying. Note a shadow line still remains and the material is completely removed.



(Figure 9) Results of hydroblaster technique on concrete while still partially wet. Note the marking material is completely removed and a shadow line still remains)

## 4.2.5 Soda Blasting



(Figure 10) Bicarbonate blasting technique on chip seal. Note the residual dust created during the blasting process.



(Figure 11) Results of soda blasting technique on chip seal. Note marking material seems completely removed and a shadow line still remains. Note, also, the residual dust on the road surface.



(Figure 12) Results of soda blasting technique on concrete. Note the marking seems completely removed and a faint shadow line still remains. Note, also, the residual dust on the road surface.

#### **5.0 DATA EVALUATION/ANALYSIS**

Data was compared in both quantitative and qualitative terms. The simplest comparison was the amount of pavement marking removed per unit time. The quantitative data factored in appearance of finished product, the effect a given technology had on the pavement (e.g. pavement was left wet, pavement was degraded, etc.), and other concerns that might arise through use of the technology (e.g. the generation of dust that obscures the road at the site).

## **6.0 CONCLUSIONS**

Given that the data was both qualitative and quantitative, data evaluation will be presented as a series of "pros" and "cons" with regards to the individual technologies.

#### 6.1.1 Dry Ice Blasting

"Pros": Dry ice blasting does not create environmental concerns. Pavement degradation on concrete was lower than any of the vehicle-mounted technologies, and the technique left no "shadow lines". "Cons": Dry ice blasting had one of the lowest distance/time removal rates of the five technologies (averaging .015 feet/second). The technology also generated considerable noise and pitted the chip seal surface.

#### 6.1.2 Carbide Grinding

"*Pros*": Removal speed of the pavement marking was the highest of the tested technologies. The surface was clean, dry, and ready for repainting immediately following grinding.

"Cons": Carbide grinding degraded the pavement during the grinding process. The grinding also left "shadow" lines, which were still visible particularly on PCC pavement.

#### 6.1.3 Diamond Bit (COMAX) Grinding

"*Pros*": Removal speed of the pavement marking was comparable to carbide grinding. The surface was clean, dry, and ready for repainting immediately following grinding.

"Cons": Diamond grinding degraded the pavement during the grinding process. The grinding also left "shadow" lines, which were still visible, particularly on PCC pavement.

#### 6.1.4 Stripe Hog Hydroblaster

"Pros": Removal speed of the pavement marking was comparable to carbide grinding. Thee Stripe Hog left no shadow lines, and caused less pavement degradation than the two grinding methods that were tested.

"Cons": The scoured surface remained wet for some time after the pavement marking removal. This could be a particular concern during periods of lower temperatures, when they drying time would increase.

#### 6.1.5 Soda Blasting

"*Pros*": Pavement degradation was lower than any of the vehicle-mounted technologies, and the technique left no "shadow lines."

"Cons": Soda blasting had one of the lowest distance/time removal rates of the five technologies (ranging from .08 ft./sec to .14 ft./sec). The technology also generates dust, which can be a potential safety hazard by lowering the visibility at the work site.

#### 7.0 RECOMMENDATIONS/IMPLEMENTATIONS

The two grinding technologies are still the most effective in removing lines quickly and providing a clean, prepared surface for marking installation. The soda and dry ice technologies should be investigated for possible use where space is limited or other specialized removal needs are present, but are not yet comparable to the production rates of the grinding or water blasting equipment. The amount of dust generated by the soda blasting technique should be factored into a manager's decision to use that technology.

The water blasting technology is the most effective at marking removal with the least amount of damage to the pavement and should be investigated for possible use by the Department.

# APPENDIX A

Technology: Diamond Grinding

Contractor: Dunn-Rite Lines (formerly Comax)

(contact information not available at the time of this writing)





# APPENDIX B

Technology: Carbide Grinding

Contractor: Interstate Barricades

858 McCormick

Layton, UT 84041-7200 (801) 546-0220



# APPENDIX C

Technology: Hydraulic Blasting

Vendor: Waterblasting Technologies

3321 SE Slater Street

Stuart, FL 34997

(877) 964-7312 Toll-Free

www.waterblastingtechnologies.com



# APPENDIX D

Technology: Dry ice

Dry Ice Blasting Service (DIBS)

2217 Cahabra Dr. Birmingham, AL

205-995-2412



# APPENDIX E

Technology: Soda Blasting

Contractor: DLP Construction Co.

Doug Parker

2927 W. 10400 S.


South Jordan, UT 84095

801-446-0890 Office

801-301-3054 Cell







## **MATERIAL SAFETY DATA SHEET**

#### **GENERAL INFORMATION**

Manufacturer:

Universal Minerals, Inc.

6319 Brookhill Drive

Houston, Texas 77087

713.797.0054 Phone

713.797.1014 Fax

#### Creation Date: 07/00



#### I. PRODUCT IDENTIFICATION

Trade Name:

MAXXSTRIP BLAST MEDIA

Formula:

Kieserite Blended Formulation

CAS No:

7487-88-9

Shipping Name:

Maxxstrip Blast Media (Not restricted article) D.O.T. Maxxstrip Blast Media (Not restricted article) I.A.T.A

#### II. INGREDIENTS

Non Hazardous:

100%

Hazardous:

None

#### III. PHYSICAL DATA

Bulk Density:

2.6 g/ cm<sup>3</sup>

Odor:

Odorless

Appearance:

Almost white

Solubility in H2O:

Yes

Ph (1% solution):

Melting Point:

1,130° C



# Universal Minerals, Inc.

6319 Brookhill Drive Houston, TX 77087 http://www.universalminerals.com Phone: 713-797-0054 Fax: 713-797-1014

#### PRODUCT DATA SHEET

#### MaxxStrip

Mineral Name:	Kieserite	
Chemistry(Dry	Basis) Typical	%
MgO	27.6 %	
S	23.0 %	
CI	0.2 %	
MgSO4	82.4 %	
CaSO4	4.2 %	
K2SO4	0.3 %	
KCI	0.3 %	
NaCl2	0.2 %	
MgCl2		
H2O ges.	12.6 %	
PH 7.0		
Water Soluble		
Mohs Hardness	3.5	
Size Range		
Coarse	Medium	<u>Fine</u>
20-40 Mesh	40-60 Mesh	60-80 Mesh

DS:MXST05.18.05